

MDCPS Facility Inspection Report Renick, Robert Ed. Ctr

District Inspection performed on 5/24/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
1	9599	M	Repair damaged sidewalk - multiple areas in front of school.	SI815123024
1	THROUGHOUT	C	Violation: Failure to maintain transfer grills to electrical rooms Correction: Provide transfer grill to electrical room throughout school. Transfer grill needs to be fuse linked (Pending from 1/09/03)	FI815104001
2	017B	M	Repair mechanical ventilation	SI815120007
2	094	M	Replace damaged light switch plate.	SI815124020
2	098	M	Recharge fire extinguisher.	SI815124017
2	94B	M	Provide escutcheon plate.	SI815124019
5	022A	M	Repair roof leak in storage.	SI815123021
5	023	M	Remove wood and provide glass in window	SI815118002
5	023	M	Provide A/C grill	SI815120014
5	025	M	Resurface with rubberized material in courtyard.	SI815123030
5	025A	M	Repair roof leak in storage.	SI815123020
5	027A	M	Repair/replace safety pads in timeout.	SI815123017
5	029B	M	Repair replace damaged sink bowl	SI815119018

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Renick, Robert Ed. Ctr

District Inspection performed on 5/24/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
5	031A	M	Repair/replace safety pads in timeout.	SI815123016
5	031B	M	Replace damaged safety pads and provide where missing	SI815120023
5	033	M	Replace damaged floor tile.	SI815124016
5	9698	M	Resurface/restripe bus drop - off.	SI815117012
5	9698	M	Relamp exterior lights at bus dropoff.	SI815123025
6	036A	M	Repair/replace damaged sink bowl - lounge.	SI815122025
6	036B	M	Repair/replace sink bowl - lounge	SI815122024
7	037B	M	Provide covebase or repair wall - mechanical.	SI815122019
7	076	M	Repair hole in wall.	SI815124012
7	080	M	Provide safety pads on wall for calm room.	SI815123028
7	083A	M	Repair hole in wall behind washing machine.	SI815124018
7	084	M	Replace damaged floor tile in corridor.	SI815123026
8	042	M	Repair covebase.	SI815123003
8	042	M	Adjust door closer to exterior - slams.	SI815123005
8	042A	M	Recharge fire extinguisher.	SI815124011

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Renick, Robert Ed. Ctr

District Inspection performed on 5/24/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
8	042B	M	Replace damaged floor tile.	SI815122011
8	042B	M	Provide ceiling tile.	SI815122012
8	043	M	Replace damaged floor tile - 043, 044.	SI815124006
8	045	M	Replace rippled carpet.	SI815122007
8	045	M	Secure light shield.	SI815124007
8	045	M	Provide covebase.	SI815124008
9	037C	M	Repair leaking air-handler.	SI815124010
9	037D	M	Repair exhaust fan - electrical.	SI815124009
9	046A	M	Repair exhaust fan - 046A, 046B - toilet rooms	SI815124005
9	046D	M	Secure loose faucet - BRR	SI815124002
9	046D	M	Repair exhaust fan - 046D, 046C - toilet rooms.	SI815124003
9	056B	M	Provide cover for junction box.	SI815124001
10	050	M	Replace damaged floor tile.	SI815124004
11	060	M	Repair expansion joint in walkway at entrance to room 060.	SI815123034
11	063	M	Provide safety on wall for calm room.	SI815123029

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900

MDCPS Facility Inspection Report Renick, Robert Ed. Ctr

District Inspection performed on 5/24/2024

Building Number	Room Number	Deficiency Type	Description/Action Taken	Deficiency Number
12	103	M	Replace flame-resistant curtains on stage - damaged.	SI815124021
12	104	M	Provide handrail on steps from stage.	SI815121013
12	110	M	Repair ceiling - water heater.	SI815124015
13	118A	M	Replace damaged carpet in weight room.	SI815122023
13	118A	M	Repair/replace panic bar - does not latch.	SI815124014
13	120	M	Repair/replace damaged sink bowl - BLR	SI815122022
13	123	M	Replace repair damaged A/C grill	SI815119034
13	9698	M	Resurface/restripe cafeteria parking area.	SI815117015
13	9699	M	Provide sunshade for bigtoy.	SI815123010

Deficiency Type

S- School Site Responsibility M- Maintenance Responsibility C- Long Term Capital Correction

Imminently dangerous conditions will be addressed immediately.

Division of Safety and Emergency Management 305-995-4900